


FILLING THE BANK

IF THE WATER IN YOUR AREA IS HIGH IN MINERAL OR SULPHUR CONTENT, TAKE THE NECESSARY STEPS TO SECURE PURE, CLEAN WATER WITH WHICH TO FILL THIS BANK AND REPLENISH THE WATER SUPPLY IN IT IF NECESSARY.

FAILURE OF THE BANK AT ANY POINT, CAUSED BY THE CORROSIVE ACTION OF IMPURE WATER, IS NOT COVERED BY THE WARRANTY.

RELIEF VALVE

FILL UNTIL WATER LEVEL
IS IN CENTER OF SIGHT GLASS.

HEATERFILLER PLUG

THE FILLER PLUG MUST BE REPLACED AND HAND TIGHTENED.
INHIBITOR

IF MORE THAN ONE THIRD OF THE BANK WATER HAS BEEN LOST BY LEAKAGE OR DISASSEMBLY FOR SERVICE, BEFORE REFILLING WITH WATER, ADD THE FOLLOWING QUANTITIES OF CALGON TYPE "CS" INHIBITOR:

BANK MODEL	QUANTITY OUNCES	BANK MODEL	QUANTITY OUNCES
L60	12	L40	8
L50	12	L20	4

KRAMER 3860 ARIZONA AVE. YUMA, ARIZONA 85365

FORM NO. 104025-99